



California Automotive Task Force Key Recommendations for Implementation of S.B. 1146




CATF includes AAIA, AERA,
APRA, ARC, ASC-CA, AUTO-
CA, AWDA, CAWA,
CASSARA, CARE, MEMA




“Fair, reasonable and nondiscriminatory price”

- The factors defined in (A) through (G) of section 1969(b)(9) only measure the costs that would be incurred by the manufacturer, but do not look at whether the information would be affordable to a small vehicle service facility that works on multiple makes and models of vehicles.




“Fair, reasonable and nondiscriminatory price”

- We urge the following two changes under section 1969(b)(9):
 - “for the purposes of section 1969, means a price that is fair, reasonable and nondiscriminatory to both buyer and seller and that allows covered persons access to parts and repair information, training and diagnostic tools; while permitting manufacturers to recover reasonable costs for providing required information and diagnostic tools considering the following:”




“Fair, reasonable and nondiscriminatory price”

- We urge the following two changes (cont'd):
 - Amendment of the following factor under section 1969(b)(9)(C), “the price charged by other motor vehicle manufacturers and other information providers for similar information.”




Reinitialization Issues

- Replace definition in section 1969(b)(10) with the following: “‘initialize’ or ‘reinitialize’ means the ability to reset the immobilizer function and/or reprogram the vehicle security system to accept the ignition key through software, hardware or any other means.”




Reinitialization Issues

- Replace section 1969(c)(4) with the following:
“On-Board Computer Initialization Procedures:
Any covered person shall have the ability to reinitialize in order to repair or remanufacture an onboard computer, whether the computer is on or off the vehicle, in the same manner and to the same extent as is available to franchised dealers and to manufacturer-authorized parts manufacturers and remanufacturers. [...more]”



Reinitialization Issues (cont'd)

- Replace section 1969(c)(4) with the following (cont'd): “For purposes of remanufacturing an onboard computer, a remanufacturer must also be provided with the ability to temporarily bypass the vehicle security system for purposes of properly testing and evaluating operation of the onboard computer.”



Standardized Web Site Terms

- Amend Section 1969(d)(3)(D) as follows: “Has clearly labeled and descriptive headings or sections that are consistent with SAE J1930, has an online index connected to a search engine and/or hyperlinks that directly take the user to the information, and has a comprehensive search engine that permits covered persons to obtain information by various query terms including, but not limited to, vehicle model, model year, vehicle identification number, motor vehicle emissions-related part number, bulletin number, diagnostic procedure, and trouble code.”